

PROPELLER MAINTENANCE RECORDS

N(53)A	Log No
Aircraft Registration No. NS 31A	
Propollor Manufacturar HARTZBLL	
Hub Model HC-I3TR-IR-	
Plada Dasian No. F7663 DR	
Hub Serial No. HK628B	
Blade Serial No's.	
1. <u>545407</u> 2. <u>545409</u> 3. <u>545413</u>	
2. 545409	
3. <u>345413</u>	
4	
Pitch Range:	
High Low	
Feather Reverse	
Governor Manufacturer HARTZBZL Model No. V5-6	
Model No. <u>V5-6</u>	
Serial No	
Date installed on aircraft	
Time Between Overhauls (TBO) Hours	
If used on multi-engine aircraft:	
□ Right □ Left □ Front □ Rear	
L Hon L Hear	



(All applicable information must be filled in)

AEROTECH PUBLICATIONS INC.

www.adlog.com P.O. Box 1359 / Southold, NY 11971-0965 (631) 765-9375 1-800-235-6444

FAX: (631) 765-9359

TOTALS-Carry forward to next page

DATE TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	FAA	rity/Country: United States		HORIZED RE	
SERVICE	OVERTINOE		tion Name and Address			
		East Coas	t Propeller Service,	Inc. 2079 Main S	Street, Lititz, PA 17543 Pho	ne:]
	-60	6. Item:	7. Description:	8.	Part Number:	5
		1	Hartzell Prop	eller	HC-I3YR-1RF/F7663DR	T
ate: May 12, 2022 opeller model HC-I3YR-1R	F serial num	12. Remarks			TIC ISTR TIGHT 1003BR	
ate. See form 8130-3 for do AINTENANCE RELEASE: The dispected in accordance worthy for return to service repair are on file at this a proved by: Shawn M. Y st Coast Propeller Service, 79 Main Street tz, PA 17543 Phone: 1-80 ail: eastcoastprop@dejazi A Repair Station E65R064Y	with regular ce for the wo agency under oung 27479 Inc. 0-875-6377	RV9 R Full de There a Compl Blade s	32, V10 R37, V11 tails are available uare no applicable A ied with applicable serial numbers: J45	R37). under Work Orde irworthiness Dire Service Bulletin 407, J45409, and	ectives at this time. s: 61-136RI, 61-281, and 61	
	V Aero right Way, ed Service Hobbs: Ser #: 3		pproved design data an			on No
Reinstall Hartzell prope	Ulor P/N HG	13d. Name (Typed or Printed):		13e. Date (dd/mmm/yyyy)	
Propeller Service under wo					User/li	ıstal
and propeller operational c s aircraft, airframe, aircraft e A and is approved for return	ngine, or ap	Where the u Block 1, it is specified in I	ser/installer performs essential that the user Block 1.	work in accordanc /installer ensures t do not constitute in	s document alone does not autome with the national regulations hat his/her airworthiness authoms stallation certification. In all circraft may be flown.	matica of an rity a
		Where the u Block 1, it is specified in I	ser/installer performs essential that the user Block 1.	work in accordanc /installer ensures t do not constitute in	e with the national regular that his/her airworthine stallation certification.	ulations ss autho

SUB-TOTALS this page

Date: May 12, 2022 Propeller model HC-I3YR-1RF serial number HK628B was overhauled this propeller model HC-I3YR-1RF serial number HK628B was overhauled this date. See form 8130-3 for details. AMINTENANCE RELEASE: The component identified above was repaired and inspected in accordance with regulations of the FAA and was found inspected in accordance with regulations of the repair are on file at this agancy under work order number: ER-15092 Approved by: Shawn M. Young 2747920 Repairman for: ast Coast Propeller Service, Inc. O79 Main Street ittit, PA 17543 Phone: 1-800-875-6377 mail: eastroastgrop@deiazzd.com AA Repair Station E65R064Y C&W Aero Services, Inc. CRS# HX1R208K 19 Wright Way, Suite #3, Fairfield, NJ 07004 (973) 227-5750 An Authorized Service Center For: Beechcraft, Mooney Aircraft & Piper W# 35556 Hobbs: 2039.7 Aircraft Tiz 2039.7 Reg. #: N531A Ser #: 3257160 Manuf.: Piper Model: PA32R-301T 1. Reinstall Hartzell propeller P/N HC-I3YR-IRF/F7663DR S/N HK628B after overhaul by East Coast Propeller Service under work order ER-15092. TSMO 0.0, Prop total time 2039.7 hrs. Engine ground run and propeller operational check OK with no leaks noted. This aircraft, airframe, aircraft engine, or appliance was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service. Permanept details are on file at this Repair Station.	DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMI			
late. See form 8130-3 to detain. AMINTENANCE RELEASE: The component identified above was repaired Maintenance RelEASE: The component identified above was found in spected in accordance with regulations of the FAA and was found in spected in accordance with regulations of the FAA and is approved by: Shawn M. Young 2747920 Repairman for: ast Coast Propeller Service, Inc. 079 Main Street titiz, PA 17543 Phone: 1-800-875-6377 mail: eastroastgrop@deiazzd.com AA Repair Station E65R064Y C&W Aero Services, Inc. CRS# HX1R208K 19 Wright Way, Suite #3, Fairfield, NJ 07004 (973) 227-5750 An Authorized Service Center For: Beechcraft, Mooney Aircraft & Piper WO # 36556 Hobbs: 2039.7 Aircraft TT: 2039.7 Reg. #: N531A Ser #: 3257160 Manuf.: Piper Model: PA32R-301T 1. Reinstall Hartzell propeller P/N HC-I3YR-1RF/F7663DR S/N HK628B after overhaul by East Coast Propeller Service under work order ER-15092. TSMO 0.0, Prop total time 2039.7 hrs. Engine ground run and propeller operational check OK with no leaks noted. This aircraft, airframe, aircraft engine, or appliance was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service. Permanept details are on file at this Repair Station. Authorized Signature: Date: 5/16/2022		SERVICE			TOTALS brought forward	ard fro	om previous page	
Authorized Signature: Jack See form 8130-310 details. Jack See form 8130-310 details. Jack See form 8130-310 details. Jack Aproach Exercise. The component identified above was repaired many formation of the FAA and was found inspected in accordance with regulations of the FAA and was found inspected in accordance with regulations of the FAA and is approved by: Jack Aproach Service for the work performed. Pertinent details of inworthy for return to service for the work performed. Pertinent details of inworthy for return to service for the work performed. Pertinent details of inworthy for return to service for the work performed. Pertinent details of inworthy for return to service for the work performed the performed by the	Date: May 1	2, 2022		3	was overhauled this			
Approved by: Shawn M. Young 2747920 Repairman for: ast Coast Propeller Service, Inc. 1079 Main Street 1079 Model: PA32R-301T 1079 Main Street 1079 Model: PA32R-301T 1079 Main Street 1079 Model: PA32R-301T 1079 Model: PA32R-301T 1079 Model: PA32R-301T 1079 Main Street 1079 Model: PA32R-301T 107	date. See for MAINTENAN and inspecte	m 8130-3 10 ICE RELEASE: d in accorda	: The compon	ent identified lations of the l	above was repaired FAA and was found One of Pertinent details of			
ititz, PA 17543 Phone: 1-800-875-6377 mail: eastroastprop@deiazzd.com AA Repair Station E65R064Y C&W Aero Services, Inc. CRS# HX1R208K 19 Wright Way, Suite #3, Fairfield, NJ 07004 (973) 227-5750 An Authorized Service Center For: Beechcraft, Mooney Aircraft & Piper WO # 35556 Hobbs: 2039.7 Aircraft TT: 2039.7 Reg. #: N531A Ser #: 3257160 Manuf.: Piper Model: PA32R-301T 1. Reinstall Hartzell propeller P/N HC-13YR-1RF/F7663DR S/N HK628B after overhaul by East Coast Propeller Service under work order ER-15092. TSMO 0.0, Prop total time 2039.7 hrs. Engine ground run and propeller operational check OK with no leaks noted. This aircraft, airframe, aircraft engine, or appliance was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service. Permanent details are on file at this Repair Station. Authorized Signature: Date: 5/16/2022	Approved by	Shawn f	M. Young 274	ny	\sim			
19 Wright Way, Suite #3, Fairfield, NJ 07004 (973) 227-5750 An Authorized Service Center For: Beechcraft, Mooney Aircraft & Piper WO # 35556	2079 Main Si ititz, PA 175 mail: eastco	treet 43 Phone: 1 pastprop@de	L-800-875-637 <u>ejazzd.com</u>	77	_			
An Authorized Service Center For: Beechcraft, Mooney Aircraft & Piper WO # 35556 Hobbs: 2039.7 Aircraft TT: 2039.7 Reg. #: N531A Ser #: 3257160 Manuf.: Piper Model: PA32R-301T 1. Reinstall Hartzell propeller P/N HC-I3YR-1RF/F7663DR S/N HK628B after overhaul by East Coast Propeller Service under work order ER-15092. TSMO 0.0, Prop total time 2039.7 hrs. Engine ground run and propeller operational check OK with no leaks noted. This aircraft, airframe, aircraft engine, or appliance was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service. Permanent details are on file at this Repair Station. Authorized Signature: Date: 5/16/2022					•			(
Reg. #: N531A Ser #: 3257160 Manuf.: Piper Model: PA32R-301T 1. Reinstall Hartzell propeller P/N HC-I3YR-1RF/F7663DR S/N HK628B after overhaul by East Coast Propeller Service under work order ER-15092. TSMO 0.0, Prop total time 2039.7 hrs. Engine ground run and propeller operational check OK with no leaks noted. This aircraft, airframe, aircraft engine, or appliance was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service. Permanent details are on file at this Repair Station. Authorized Signature: Date: 5/16/2022	140	An Autho	orized Servic	ce Center For	: Beechcraft, Mooney			_
Propeller Service under work order ER-15092. TSMO 0.0, Prop total time 2039.7 hrs. Engine ground run and propeller operational check OK with no leaks noted. This aircraft, airframe, aircraft engine, or appliance was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service. Permanent details are on file at this Repair Station. Authorized Signature: Date: 5/16/2022							Model: PA32R-301T	<u> </u>
	Propeller and prop This aircraft FAA and is a	Service und eller operation airframe, aircapproved for re	der work order onal check OK craft engine, or eturn to service	ER-15092. TS with no leaks appliance was r Permanent de	noted. epaired and inspected in accordatils are on file at this Repair S	9.7 hr	rs. Engine ground run	he
	1		(1				

TOTALS-Carry forward to next page