

## PROPELLER MAINTENANCE RECORDS

	Log No
Aircraft Registration No	
Propeller Manufacturer	
Hub Model HC - I 3 YR - 1 RF	
Blade Design No	
Hub Serial No	
Blade Serial No's.	
1	
2	
3	
4	
Pitch Range:	
High Low	
Feather Reverse	
Governor Manufacturer	
Model No	
Serial No.	
Date installed on aircraft	
Time Between Overhauls (TBO) Hours	<del></del>
If used on multi-engine aircraft:	
☐ Right ☐ Left	
☐ Front ☐ Rear	



(All applicable information must be filled in)

## AEROTECH PUBLICATIONS INC.

www.adlog.com P.O. Box 1359 / Southold, NY 11971-0965

(631) 765-9375 1-800-235-6444 FAX: (631) 765-9359

	SERVICE	OVERHAUL TIME	Advanced Aircraft Service  8622 Gibbs Dr.
			Advanced Aircraft Service
			Advanced Aircraft Service
_			
_			San Diego, CA. 92123
			858-560-7599 Fax 858-560-7507
			CESSNA SERVICE CENTER
<del></del>			Date:4/17/15 N# :N616AR S/N:Prop HK1201B
			Hobbs: 794.6 hr TT: 794.6 hr TTSMOH: N/A
		This Pron has	s been inspected I/A/W FAR Part 43 Appendix D. using
		•	aft Maintenance Manual as a guide to complete an Annual
			nd was determined to be in an airworthy condition at this time.
		inopconon, an	The state determined to be in an antioning condition at this time.
			IA3467663
			END
			Advanced Aircraft Service
		_	8622 Gibbs Dr.
		_	San Diego, CA. 92123
		-	858-560-7599 Fax 858-560-7507
		- \ D=4=+0	CESSNA SERVICE CENTER
		Date:6	
			:874.2 hr TT:874.2 hr TTSMOH:
			after motor repair, Installed new mounting oring gine has been inspected I/A/W FAR Part 43 Appendix D. using
			Maintenance Manual as a guide to complete an 100 hr/Annual
			vas determined to be in an airworthy condition at this time.
		. 4	IA3467663
			END
			Advanced Aircraft Service
			8622 Gibbs Dr.
			San Diego, CA. 92123
			858-560-7599 Fax 858-560-7507
		r	FSSNA / BEECHCRAFT SERVICE CENTER
İ			e:7/21/17 N# :N616AR S/N:Prop HK1201B
		Hot	obs:942.8 hr TT:942.8 hr TTSMOH:
		This Drop has he	pen inspected I/A/W FAR Part 43 Appendix D. using
		Correct Aircraft	Maintenance Manual as a quide to complete an Alliuai
		Inspection, and	was determined to be in an airworthy condition at this time.
		- '	
			IA3467663
			SUB-TOTALS this page

## International AeroTech Academy For Training Purposes Only

		Advanced Aircraft Service 8622 Gibbs Dr. San Diego, CA. 92123 858-560-7599 Fax 858-560-7507	Page No
DATE	TOTAL TIME IN SERVICE	CESSNA / BEECHCRAFT SERVICE CENTER  Date:8/10/18 N#:N616AR S/N:Prop HK1201B  Tach:1001.5 hr TT:1001.5 hr TTSMOH:  nis Prop has been inspected I/A/W FAR Part 43 Appendix D. using	- RMING WORK
		urrent Aircraft Maintenance Manual as a guide to complete an Annuspection, and was determined to be in an airworthy condition at this	al time.
		IA3467663 END	
		Advanced Aircraft Service 8622 Gibbs Dr.	
		8022 Globs Dr. San Diego, CA. 92123	
		858-560-7599 Fax 858-560-7507	
		CESSNA / BEECHCRAFT SERVICE CENTER	
		Date:3/21/19 N#:N616AR S/N:Prop HK1201B	
	Thic	Tach:1004.8 hr TT:1004.8 hr Prop has been inspected I/A/W FAR Part 43 Appendix D. using	
		ent Aircraft Maintenance Manual as a guide to complete an Annual	
-		ction, and was determined to be in an airworthy condition at this tim	e -
	шэрс	outer, and was determined to be in an an worthy contained at time time	
		IA3467663	
		END	
[ D 1 7			
N616	etkus SAR S/ M/N: HC-I	April 15,2020 N: 3257423 TOTAL TIME: 1061.4 MX HOBBS :1061.4 3YR-1RF S/N: MK1201B PROP TSMO: 1061.4	1
N616 Prop I Comp	M/N: HC-I olied with 10 leted pre-ins	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS :1061.4	
N616 Prop I Comp Compi Noted  I certifal	M/N: HC-I olied with 10 leted pre-ins current time	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4 3YR-1RF S/N: MK1201B PROP TSMO: 1061.4 00hr Inspection in accordance with Piper Service Manual. pection operational checks. Performed inspection including propeller, and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and w	associated components.
N616 Prop I Comp Compi Noted I certif airwor Gerald	M/N: HC-I blied with 10 leted pre-ins current time fy that this p	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4  3YR-1RF S/N: MK1201B PROP TSMO: 1061.4  10hr Inspection in accordance with Piper Service Manual.  pection operational checks. Performed inspection including propeller, and is and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and w  A&P3455625IA	associated components.
N616 Prop I Comp Compi Noted  I certif airwor Gerald  Corporation 15452 - Airg Burlington,	M/N: HC-I blied with 10 leted pre-ins current time fy that this p thy conditio d A Olson  te Air Cen  port Drive WA 98233	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4 3YR-1RF S/N: MK1201B PROP TSMO: 1061.4 60hr Inspection in accordance with Piper Service Manual. pection operational checks. Performed inspection including propeller, and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and with the 10	associated components.  as determined to be in
N616 Prop I Comp Compi Noted  I certif airwor Gerald  Corporation 15452 - Airg Burlington,	M/N: HC-I blied with 10 leted pre-ins current time fy that this p rthy conditio d A Olson  te Air Cen  port Drive WA 98233 757-7757	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4 3YR-1RF S/N: MK1201B PROP TSMO: 1061.4 60hr Inspection in accordance with Piper Service Manual. pection operational checks. Performed inspection including propeller, and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and with the 10	associated components.  as determined to be in  Date 04/28/2021
N616 Prop I Comp Compi Noted  I certif airwor Gerald  Corporat  15452 – Airr Burlington, Phone (360) Fax (360) 7  Airframe: 11 Hobbs: 1129 Engine: 1129	M/N: HC-I blied with 10 leted pre-ins current time fy that this p rthy conditio d A Olson  te Air Cen  port Drive WA 98233 757-7757 757-1557	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4  3YR-1RF S/N: MK1201B PROP TSMO: 1061.4  Othr Inspection in accordance with Piper Service Manual.  pection operational checks. Performed inspection including propeller, and is and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and w  A&P3455625IA  ter N616AR Model: PA32R-301T S/N3257423  Prop: HC-I3YR- 1RF S/N: HK1201B  Complied with 100HR inspection in accordance with FAR 43 appendix D using application and ICA Instructions. Including Piper PA32R-301T manual. Lubed with Aeros Grease and dressed blades.  This Propeller has been inspected in accordance with a 100HR inspection and has been	associated components.  as determined to be in  Date 04/28/2021
N616 Prop I Comp Compi Noted  I certif airwor Gerald  Corporat  15452 – Airr Burlington, Phone (360) Fax (360) 7  Airframe: 11 Hobbs: 1129 Engine: 1129	M/N: HC-I blied with 10 leted pre-ins current time fy that this p rthy conditio d A Olson  te Air Cen  port Drive WA 98233 757-7757 757-1557	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4  3YR-1RF S/N: MK1201B PROP TSMO: 1061.4  Ohr Inspection in accordance with Piper Service Manual.  pection operational checks. Performed inspection including propeller, and as and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and wards.  A&P3455625IA  Terror N616AR Model: PA32R-301T S/N3257423  Prop: HC-I3YR- 1RF S/N: HK1201B  Complied with 100HR inspection in accordance with FAR 43 appendix D using application manuals and ICA Instructions. Including Piper PA32R-301T manual. Lubed with Aeros Grease and dressed blades.  This Propeller has been inspected in accordance with a 100HR inspection and has been be in an airworthy condition.	associated components.  as determined to be in  Date 04/28/2021  able shell 5 found to
N616 Prop I Comp Comp Noted I certifi airwor Gerald  Corporate  15452 - Airp Burlington, Phone (360)	M/N: HC-I blied with 10 leted pre-ins current time fy that this p rthy conditio d A Olson  te Air Cen  port Drive WA 98233 757-7757 757-1557	N: 3257423 TOTAL TIME: 1061.4 MX HOBBS:1061.4  3YR-1RF S/N: MK1201B PROP TSMO: 1061.4  Ohr Inspection in accordance with Piper Service Manual.  pection operational checks. Performed inspection including propeller, and as and inspection needs provided to owner.  ropeller has been inspected in accordance with the 100hr Inspection and wards.  A&P3455625IA  Terror N616AR Model: PA32R-301T S/N3257423  Prop: HC-I3YR- 1RF S/N: HK1201B  Complied with 100HR inspection in accordance with FAR 43 appendix D using application manuals and ICA Instructions. Including Piper PA32R-301T manual. Lubed with Aeros Grease and dressed blades.  This Propeller has been inspected in accordance with a 100HR inspection and has been be in an airworthy condition.	associated components.  as determined to be in  Date 04/28/2021  able shell 5 found to

SUB-TOTALS this page

TOTALS-Carry forward to next page