HARTZELL

## PROPELLER LOGBOOK

PROPELLER MODEL HC-I3YR-IRF

PROPELLER S/N HK758B

LOGBOOK #\_\_\_\_

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

## PROPELLER MAINTENANCE RECORD

Position	PITCH RANGE
Propeller Model	High/Feather
Propeller S/N	Start Lock
Blade Design	Low
Blade S/N's	Reverse
No. 1	
No. 2	Aircraft Manufacturer
No. 3	Aircraft Model
No. 4	S/N
No. 5	Registration
No. 6	

Spinner Assembly Part No. \_\_\_\_\_

9-27-87	924.8 Ms.	Kemoved propeller from A/C sent To
		MAXWELL AIRERAFT SERviced For Overhauel
		Installed Propoller TAW PIPER SERVICE
		MANUAL, GRA RAW & checked OK FOR SORVICE
		MAINTENANCE RELEASE  The aircraft and/or component was repaired and inspected in accordance with current F.A.R.'s and was found airworthy for return to service. Pertinent details of the repair are on file under work order:  No. 120  Date 12701 Signed 120 for  Authorized Signature
		F.A.A APPROVAL REPAIR STATION NO Q6UR446Y
		Monaco Air Duluth LLC,  4535 Airport Approach Rd Duluth, MN 55811
		MAINTENANCE RELEASE
		TYPE OF UNIT Propeller SERIAL No. HK- 2588
		MODEL HC-I3YR-1RF/F7663DB
		The component identified above was repaired and inspected in accordance with current Regulations of the Federal
		Aviation Administration and is approved for return to service.
		Pertinent details of the repair are on file at this agency under WORK ORDER No. 113 191 DATE 9-21-07
		SIGNED Comit & mugael of FOR
		MAXWELL AIRCRAFT SERVICE NC.
	-	CRYSTAL AIRPORT • MINNEAPOLIS, MINN. 55429
		FAA Approved Repair Station No. UF2R211 (over)
		Aircraft: N3HY; Type: PA-32R-301T; S/N: 3257252; Hobbs: 1060.20; Tach: 1060.20; Total
	Shop Order #: 08-	
	and inspected spir	ner.
	current FAR's and	ne, aircraft engine, propeller, or appliance was repaired and inspected in accordance with was found to be airworthy for return to service. Pertinent details of the repair are on file at this
	<ul><li>Certified Repair Si</li><li>Monaco Air Duluth</li></ul>	ation Q6UR446Y. LLC - 4535 Airport Approach Rd Duluth, MN 55811
	(218) 727-2911 Signature:	Cames Import
		10P27511B6 IA
	- <u>'</u>	4535 Airport Approach Rd Duluth MN 55811 (218) 727-2911
	MONACC	Cirrus Authorized Service Center Cessna Authorized Service Facility
		ircraft: N3HY; Type: PA-32R-301T; S/N: 3257252; Hobbs: 1213.1; Total Time: 1213.1; Prop :-I3YR-1RF, S/N: HK758B, Time: 1213.1, SMOH: 1213.1
	Removed spinner. I	aspected prop hub, spinner, and spinner baulkhead. Filed small nicks from propeller blades.
	,	peller has been inspected in accordance with an annual/100 hour inspection and was
	determined to be in	an airworthy condition.
		Our of the
	Signature:	5 J. Imberg A&P 2751176 IA
		Page 3

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Propeller

TSN

TSO

Date

A/C

Hrs

Blade Ser. Plas. J 62017, J 62018, J 62021 (everhanted propeller in accordance with Hartzell Manuals 113B Bevision 33, 133 C Revision 22 + 202 A Bevision 31. Complied with Hartzell Belletins 118F + 136I. Camplied with Hartzell Servere Letters 614 Bersian 1, 189 Bersian 2, 217, 229 + 244. Camplied with Hartzell Instructions 152A.

 Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
	<b>3eeg</b> uality Serv Since 194		
		GREELEY, CO REPAIR STATION BX4R092M (970) 353-9200	
. 06-18-10 AFTT 1266.		1266.50 Hobbs 1266.50 N3HY sn 3257252 Eng TTSFRM 0.00 Prop TTSN 1266.50 TSMOH 0.00	
J62018, blace Services, Incompanies of Spinner pn 5 "I certify thi	de #2 sn e. CRS# 87-741.	ropeller Model # HC-13YR-1RF/F7663DR sn HK758B blade #1 sn J62017, blade #3 sn J62021 after overhaul from Precision Propeller # UB3R887L WO# 15746. Replaced spinner bulkhead pn 758-563 and . Torqued and saftied propeller as required.	
inspection p	er FAR	43 Appendix D and found to be in an airworthy condition".	
		Ginn Ginn	
Aviation A Pertinent	dminist	epaired and inspected in accordance with current regulations of the Federal tration and is approved for return to service.  on file at Beegles Aircraft Service, Inc., Greeley, CO.  295 CRS# BYAR092M	
Aviation A	dminist	on file at Beegles Aircraft Service, Inc., Greeley, CO. ,295 CRS# BX4R092M	

Page 5

ate	Prc 4535 Airport Approach Rd D uth 4 (5)811  TSN MONACO ATR Circus Authorized Service Cen :*	es, ctions.	
	Date: 10/05/2015: Aircraft: N3HY; Type: PA-32R-301T S. N: 3257252; Hobbs: 1640.5; Total Time: 1640.5; Prop		
-	Type: HC-I3YR-1RF, S/N: HK758B, Time: 1640.5. SM*24: 374.0 Shop Order #: 15-9258	-	
	Performed Annual/100 Hr. inspection of propellor IAW > - 2R-301T AMM section 5-20-00 inspection checklist and PA-32R-301T AMM.		_
	Researched ADs thru current Bi-Weekly 2015-19. Inspected spinner, hub and blades. No blade nicks noted this time.		
	certify that this Propeller has been inspected in accordance with an Annual / 100 hr inspection and was determined to be in an airworthy condition.		
	Signature: James Om Verg		
	James Imberg A&P 2751176		
-		-	
		-	
	Table 1 Late		
	The state of the s		
	Record to the same of the same		
_	agent a process as a substitute condition.	-	-
	General James Invest		
-	4535 Airport Approach Rd, Duluth, MN 55811 (218) 727-2911 Cirrus Authorized Service Center		
	Cessna Authorized Service Facility  Date: 10/02/2017; Aircraft: N3HY: Type: PA-32R-301T; S/N: 3257252; Hobbs: 1716.3; Total Time: 1716.3; Prop -		
	Type: HC-I3YR-1RF, S/N: HK758B, Time: 1716.3, SMOH: 449.8		
	Shop Order #: 17-9940 Performed Annual/100 Hr. inspection of propellor IAW PA-32R-301T AMM section 5-20-00 inspection checklist		
	and PA-32R-301T AMM. Researched ADs thru current Bi-Weekly 2017-18.		_
	Inspected and cleaned spinner, hub and blades, dressed out minor nicks as necessary. Greased prop hub.  I certify that this Propeller has been inspected in accordance with an Annual / 100 hour inspection and was		
	determined to be in an airworthy condition.		
	Signature: Almus Com VIII		
	James Imberg A&P 2751176		-
-			
	4535 Airport Approach Rd Duluth MRI 55811 213) 727 0911 Dirtus Authorized Service Center Cessina - Uthorized Service Facility		
-	Date: 10/05/2018; Aircraft: N3HY; Type: PA-32R-301T, S/N: 3257252; Hobbs. 1844 2; Total Time. 1844 2; Prop - Type. HC-I3YR-1RF, S/N. HK758B, Time. 1844 2, SMOH 577 7		
	Shop Order #: 18-10245  Performed Annual 100 Hr inspection of propellor IAW PA-32R-301T AMM section 5-20-00 inspection checklist		
	and PA-32R-301T AMM. Researched ADs thru current Bi-Weekly 2018-19.		
	Inspected spinner, hub and blades, Greased hub, No blade nicks at this time. I certify that this Propeller has been inspected in accordance with an Annual / 100 hour inspection and was		
	determined to be in an airworthy condition.		
	Signature Allmin Indian		
	mes Imberg A&P 27511/6 Z >2		

Page 6

Date	TSN ACNACOALR Circus Authorized Service Center	tions.
	Date. 9/27/2019; Aircraft: N3HY, Type: PA-32R-301T, S/N; 3257252; Hobbs: 1897.7, Total Time. 1897.7, Prop- Type: HC-l3YR-1RF, S/N: HK758B, Time: 1897.7, SMOH: 631.2	
	Shop Order # 19-10592 Performed Annual / 100 Hour inspection of propellor IAW PA-32R-301T AMM section 5-20-00 inspection	
	checklist and PA-32R-301T AMM.	
	Researched ADs thru current Bi-Weekly 2019-19.  Inspected spiriner, hub and blades. Greased hub. No blade nicks at this time. Dressed out minor nicks as	100
	necessary I certify that this Propeller has been inspected in accordance with a 100 hour inspection and was determined to be	
	in an airworthy condition	
	Signature: Sames Imberg A&P 2751176 ZD	
	4535 Airport Approach Rd Duluth MN 55811 C18) 727-2911 Circus Authorized Service Center	
	Date: 9/11/2020, Aircraft, N3HY: Type. PA-32R-301T, S/N, 3257252; Hobbs: 1956,1; Total Time: 1956,1, Prop- Type: HC-I3YR-1RF, S/N, HK758B, Time, 1956,1, SMOH, 689,6 Shop Order # 20-10878	
	Performed Annual / 100 Hour Inspection of propellor IAW PA-32R-301T AMM section 5-20-00 inspection	
	checklist and PA-32R-301 T AMM.	
	Researched ADs thru current Bi-Weekly 2020-18.	
-	Inspected spinner hub and blades. Greased hub. Dressed out minor nicks as necessary  I certify that this Propeller has been inspected in accordance with a 100 hour inspection and was determined to be	
	in an airworthy condition	
	Signature Complete Complete	
	Signature Sames Imberg A&P 275 176 Zp	
	4535 Airport Approach Rd Duluth MN 55811	
	(218) 727-2911  Cirrus Authorized Service Center	
	Date: 10/05/2021; Aircraft: N3HY; Type: PA-32R-301T; S/N: 3257252; Hobbs: 2015.6; Total Time: 2015.6; Prop -	
	Type: HC-l3YR-1RF, S/N: HK758B, Time: 2015.6, SMOH: 749.1 Shop Order #: 21-11228	
	Performed Annual / 100 Hour Inspection of propellor IAW PA-32R-301T AMM section 5-20-00 inspection	
-	checklist and PA-32R-301T AMM, Researched ADs thru current Bi-Weekly: 2021-19.	
	Inspected spinner, hub and blades. Greased hub, No blade nicks at this time.  I certify that this Propeller has been inspected in accordance with a 100 Hour Inspection and was determined to	
	be in an airworthy condition.	
	Signature: Sames Imberg A&P 2791176	